


Jobsite Safety Guidelines

COVID-19 Best Practices:



SOCIAL DISTANCING - 6 FT



WEAR THE REQUIRED PPE



STAY HOME IF YOU'RE SICK



DISINFECT ALL SURFACES



COVER COUGHS & SNEEZES



WASH HANDS FREQUENTLY

Employer Responsibilities

- A site-specific COVID-19 Supervisor shall be designated by the contractor at every job site to monitor the health of employees and enforce the COVID-19 job site safety plan.
- A daily attendance log of all workers and visitors must be kept and retained for at least four weeks.
- Check health and temperature of each worker and visitor coming on the jobsite.
- Send anyone home who shows signs of being sick (fever, cough, shortness of breath).
- Ensure workers maintain 6-ft distancing unless it would create an imminent safety hazard.
- Provide training, at least weekly, to explain the protective measures in place for all workers. Social distancing must be maintained at all gatherings.
- Provide personal protective equipment (PPE) such as gloves, goggles, face shields and face masks as appropriate, or required, for the activity being performed.
- Provide handwashing stations with soap and running water. When running water is not available, portable washing stations, with soap, are required, per WAC 296-155-140 2(a) (f).
- Frequently clean and disinfect high-touch surfaces on job sites and in offices, such as shared tools, machines, vehicles and other equipment, handrails, doorknobs, and portable toilets.
- Ask workers to self-identify symptoms of fever, coughing, or shortness of breath each day, before the shift, mid-shift, and at home.

Under the authority of the Washington Industrial Safety and Health Act (WISHA), L&I's Division of Occupational Safety and Health (DOSH) will enforce these COVID-19 jobsite safety and health requirements. Complaints be submitted to the L&I Call Center (1-800-423-7233) or via e-mail to Linda Adame at adag235@lni.wa.gov.

DESIGNATED COVID-19 Supervisor:

Name:

Company:

Phone: